

Report ID:	28,104,306	Version:	1
Created:	13 Apr 2026		


Make:	Honda	Model:	CRV
Body Style:	SUV	Year:	2003
Rego No.:	BQQ841	Rego Expiry:	26 Aug 2026
WoF Expiry:	09 Jul 2026	Odometer:	257,793 Kms
Good No.:	28104306	VIN:	JHLRD78404C201827
Next Service:	260,100kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Minor spider rust on roof. Paint of rear bumper is flaking. Under bonnet is rusty.

Conditions During Body Inspection

Dry

Under Carriage and Under Bonnet Inspection Comments

Leaking from right front drive shaft boots.

Interior Comments

Seats:	Small hole on driver's base pad.
Carpets:	Average
Panels:	Good
Dashboard:	Good

General Comments

Oil level is just above minimum line. AC is not cold. Suspensions are rattling (positive front upper mount bushes and rear sway bar bushes). Driver's door lock actuator is not operating.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Yuki Itohara		
Published by:	Tiaan Pienaar		
Inspection Date:	13 Apr 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			7.0 mm
Right front			7.0 mm
Left rear			8.0 mm
Right rear			8.0 mm
Spare		Yes	
Suspension			
Suspension performance		✓	
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____