

Report ID:	28,112,130	Version:	1
Created:	11 Apr 2026		


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2017
Rego No.:	KHJ731	Rego Expiry:	14 Jun 2026
WoF Expiry:	10 Feb 2027	Odometer:	240,932 Kms
Good No.:	28112130	VIN:	MMAWYKL10HH001259
Next Service:	254300	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front step plates worn. Front sills paint worn. L sill dents. L running board dented. Rear of cab dented. Left rear seatbelt missing. Left front seatbelt frayed. Good liner stained. Drivers door seal torn.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	LR seat base missing.
Carpets:	Average
Panels:	Average
Dashboard:	heater control knob missing

General Comments

Vehicle not test driven, no coolant in vehicle. Evidence of coolant leak from block. Oil leak from turbo.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Darren Beban	
Published by:	Darren Beban	
Inspection Date:	11 Apr 2026	

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes			✓
Engine performance			✓
Noise			✓
Coolant condition		✓	
Cooling performance			✓
Radiator / Hoses (visual)	✓		
Transmission			
Operation			✓
Noise			✓
Clutch			✓
CV joints			✓
Wheel bearings	✓		
Brakes			
Performance			✓
Hand brake			✓
Tyres (lowest observed tread depth of tyres)			
Left front			6 mm
Right front			3 mm
Left rear			4.5 mm
Right rear			3.5 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____