


Report ID:	28,115,496	Version:	1
Created:	14 Apr 2026		

Make:	Volkswagen	Model:	Polo
Body Style:	Hatchback	Year:	2020
Rego No.:	MYR142	Rego Expiry:	15 Jul 2026
WoF Expiry:	24 Jul 2026	Odometer:	33,082 Kms
Good No.:	28115496	VIN:	WVWZZZAWZLU096290
Next Service:	43000	Service History:	Yes

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Goodd

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

Good

**Interior Comments**

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

**General Comments**

Goodd

Road Conditions During Test Drive	Dry
-----------------------------------	-----

Engine Timing Mechanism	Timing Chain
-------------------------	--------------

Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
----------------------------------	--	-----

Inspected by:	AI Osmena
---------------	-----------

Published by:	AI Osmena
---------------	-----------

Inspection Date:	14 Apr 2026
------------------	-------------

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5 mm
Right front			5 mm
Left rear			5 mm
Right rear			5 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide: **NAME** \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_