


| | | | |
|------------|-------------|----------|---|
| Report ID: | 28,123,785 | Version: | 1 |
| Created: | 20 Apr 2026 | | |

| | | | |
|---------------|---------------------|------------------|-------------------|
| Make: | Mazda | Model: | Demio |
| Body Style: | Hatchback | Year: | 2013 |
| Rego No.: | NWN522 | Rego Expiry: | 25 Jun 2026 |
| WoF Expiry: | 14 Nov 2026 | Odometer: | 113,181 Kms |
| Good No.: | 28123785 | VIN: | 7AT0C12HX21146418 |
| Next Service: | 15/5/26 or 121000km | Service History: | No |

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Stone chips in windscreen.

Conditions During Body Inspection

Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

| | |
|------------|---------|
| Seats: | Average |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Good |

General Comments

Vehicle drove well.
 Centre console box broken, doesn't fold down.

Road Conditions During Test Drive

Dry

Engine Timing Mechanism

Timing Chain

Evidence of Cam Belt Replacement

Yes No

Kms

Inspected by: Aaron Johnson

Published by: Aaron Johnson

Inspection Date: 20 Apr 2026

| | OK | Requires Attention | N/A |
|---|----|--------------------|------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | | 5 mm |
| Right front | | | 5 mm |
| Left rear | | | 5 mm |
| Right rear | | | 5 mm |
| Spare | | No | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | | | ✓ |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____