


Report ID:	28,129,575	Version:	1
Created:	24 Apr 2026		

Make:	Holden	Model:	Astra
Body Style:	Hatchback	Year:	2009
Rego No.:	EUZ394	Rego Expiry:	29 Jul 2026
WoF Expiry:	29 Oct 2026	Odometer:	183,551 Kms
Good No.:	28129575	VIN:	W0L0AHL0885096094
Next Service:	180482	Service History:	No

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Front bumper left side damaged  
 Minor stonechips on windscreen

Conditions During Body Inspection    Dry

### Under Carriage and Under Bonnet Inspection Comments

Front wheel drive  
 Oil leak  
 Front crash sensor loose

### Interior Comments

Seats:	Good
Carpets:	Good
Panels:	driver side door card damaged
Dashboard:	Good

### General Comments

ABS and Traction Control light on  
 Due for service  
 Rear left fog light not working

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Cambelt	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No    Kms
Inspected by:	Cameron Senior-Arnold	
Published by:	Janine Bell	
Inspection Date:	20 Apr 2026	

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			7.0 mm
Right front			5.7 mm
Left rear			4.4 mm
Right rear			6.4 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_