


Report ID:	28,139,766	Version:	1
Created:	24 Apr 2026		

Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2017
Rego No.:	KRH57	Rego Expiry:	29 Jun 2026
WoF Expiry:	25 Jul 2026	Odometer:	128,262 Kms
Good No.:	28139766	VIN:	MMAZJKL10HH012234
Next Service:	132000	Service History:	No

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Right rear door glazing rust, rear left interior grab handle missing, right rear interior grab handle need to refit, both side step guard dents, taillights moist, left wing mirror cover missing, right front wheel flair damage, front antenna broken,

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Bull bar bent can't open the bonnet, underbody rust, skid plate damage, left inner front cv boot split, exhaust pipe rusty,

Interior Comments

Seats:	driver seat torn,
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Dpf light on,

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Curshey Accad
Published by:	Curshey Accad
Inspection Date:	24 Apr 2026

	OK	Requires Attention	N/A
Engine			
Oil level			✓
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition			✓
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			4 mm
Right front			4 mm
Left rear			4 mm
Right rear			4 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____