

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 28,142,069  | Version: | 1 |
| Created:   | 24 Apr 2026 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Mazda       | Model:           | Axela             |
| Body Style:   | Hatchback   | Year:            | 2014              |
| Rego No.:     | RBW460      | Rego Expiry:     | 19 May 2026       |
| WoF Expiry:   | 29 Jan 2027 | Odometer:        | 129,427 Kms       |
| Good No.:     | 28142069    | VIN:             | 7AT0C13JX25111950 |
| Next Service: | 135,000 km  | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Tyre mobility kit available

Conditions During Body Inspection

Dry

### Under Carriage and Under Bonnet Inspection Comments

Fwd

### Interior Comments

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

### General Comments

Road Conditions During Test Drive    Dry

Engine Timing Mechanism    Timing Chain

Evidence of Cam Belt Replacement     Yes     No    Kms

Inspected by:    Vasanthakumar Mayilswamy

Published by:    Vasanthakumar Mayilswamy

Inspection Date:    24 Apr 2026

|   | OK | Requires Attention | N/A  |
|---|----|--------------------|------|
| <b>Engine</b>                                       |    |                    |      |
| Oil level   | ✓  |                    |      |
| Smoke & fumes                                       | ✓  |                    |      |
| Engine performance                                  | ✓  |                    |      |
| Noise   | ✓  |                    |      |
| Coolant condition                                   | ✓  |                    |      |
| Cooling performance                                 | ✓  |                    |      |
| Radiator / Hoses (visual)                           | ✓  |                    |      |
| <b>Transmission</b>                                 |    |                    |      |
| Operation   | ✓  |                    |      |
| Noise   | ✓  |                    |      |
| Clutch  |    |                    | ✓    |
| CV joints   | ✓  |                    |      |
| Wheel bearings                                      | ✓  |                    |      |
| <b>Brakes</b>                                       |    |                    |      |
| Performance   | ✓  |                    |      |
| Hand brake  | ✓  |                    |      |
| <b>Tyres (lowest observed tread depth of tyres)</b> |    |                    |      |
| Left front  |    |                    | 3 mm |
| Right front   |    |                    | 3 mm |
| Left rear   |    |                    | 5 mm |
| Right rear  |    |                    | 5 mm |
| Spare   |    | N/A                |      |
| <b>Suspension</b>                                   |    |                    |      |
| Suspension performance                              | ✓  |                    |      |
| Steering performance                                | ✓  |                    |      |
| Shock absorbers                                     | ✓  |                    |      |
| <b>Air Conditioning / Heater</b>                    |    |                    |      |
| Operation   | ✓  |                    |      |
| <b>Electrical / Accessories</b>                     |    |                    |      |
| Head lights   | ✓  |                    |      |
| Tail lights   | ✓  |                    |      |
| Indicators  | ✓  |                    |      |
| Dashboard warning lights                            | ✓  |                    |      |
| Wipers (front & rear)                               | ✓  |                    |      |
| Window winder FL                                    | ✓  |                    |      |
| Window winder FR                                    | ✓  |                    |      |
| Window winder RL                                    | ✓  |                    |      |
| Window winder RR                                    | ✓  |                    |      |
| Rear view mirrors                                   | ✓  |                    |      |
| Radio (basic test only)                             | ✓  |                    |      |
| CD (basic test only)                                | ✓  |                    |      |
| Number of keys                                      | 1  |                    |      |
| Central locking                                     | ✓  |                    |      |
| Remote locking                                      | ✓  |                    |      |
| Sat. nav. (basic test only)                         |    |                    | ✓    |
| Reversing camera                                    | ✓  |                    |      |

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_