

Report ID:	28,146,610	Version:	1
Created:	29 Apr 2026		


Make:	Mitsubishi	Model:	L300
Body Style:	Van	Year:	1998
Rego No.:	XA5156	Rego Expiry:	20 May 2026
WoF Expiry:	31 Aug 2026	Odometer:	339,454 Kms
Good No.:	28146610	VIN:	7A1PM5J38WP039021
Next Service:	341,000km	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front grille is broken. LF indicator lens is cracked. Rust in left A-pillar. LR taillight is cracked. Right front inner wheel arch is dented. Stone chip in the windscreen. Holes in roof filled in with silicone. Front & rear wheels are mis-matched.

Conditions During Body Inspection: Dry

Under Carriage and Under Bonnet Inspection Comments

Engine oil leaks.
 RR shock is leaking.

Interior Comments

Seats:	Average, drivers seat is torn.
Carpets:	Average
Panels:	Average
Dashboard:	Average, clutch pedal rubber missing.

General Comments

Unable to read sticker that shows when Cambelt was replaced.
 RF park light not working. Engine runs rough & is very smoky.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Kms
Inspected by:	Blair Robertson
Published by:	Blair Robertson
Inspection Date:	29 Apr 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes		✓	
Engine performance		✓	
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			3.5 mm
Right front			5 mm
Left rear			5.5 mm
Right rear			7.5 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation			✓
Electrical / Accessories			
Head lights		✓	
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking			✓
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____