


Report ID:	28,149,455	Version:	1
Created:	06 May 2026		

Make:	BMW	Model:	X1
Body Style:	Wagon	Year:	2011
Rego No.:	RGY509	Rego Expiry:	09 Nov 2026
WoF Expiry:	07 Oct 2026	Odometer:	177,370 Kms
Good No.:	28149455	VIN:	WBAVL32040VP94917
Next Service:	172,458 km	Service History:	No

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Rear reverse camera damaged.
 Headliner sagging.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

RWD, Excessive oil leak underside.
 Suspect 1 of the engine pulleys making a whining noise on load and on idle.
 Coolant reservoir internal floater gauge for coolant level broken - Coolant level in reservoir low.

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Poor
Dashboard:	Average

General Comments

Suspect Fuel gauge or unit faulty digital reading fluctuating.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Imraan Bryant		
Published by:	Erin White		
Inspection Date:	01 May 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition		✓	
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			2.0 mm
Right front			2.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare		N/A	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____