

Report ID:	28,159,376	Version:	1
Created:	04 May 2026		


Make:	Holden	Model:	Commodore
Body Style:	Wagon	Year:	2011
Rego No.:	FSQ402	Rego Expiry:	04 Jul 2026
WoF Expiry:	08 Oct 2026	Odometer:	214,070 Kms
Good No.:	28159376	VIN:	6G1EK8EV3BL513369
Next Service:	215063 kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Headlights yellowed. W/S delaminating. W/S rubber edges perishing. Rear W/S tint bubbling. Roof aerial missing. Boot lid struts weak. RF door check strap clicks. Rear tyres worn to wear bars. LF tyre sidewall damage.

Conditions During Body Inspection: Dry

Under Carriage and Under Bonnet Inspection Comments

Engine major oil leaks. Underbody surface rust, rear subframe area quite bad. Front sway bar links boots split.

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Average
Dashboard:	Good

General Comments

Service due. Steering wheel wear. Left side mirror adjustments not working. Steering knocks. Brake lights not working. Slight misfire on cold start. Braking power weak.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Eleoit Kumar		
Published by:	Eleoit Kumar		
Inspection Date:	04 May 2026		

OK Requires Attention N/A

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance		✓	
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			6 mm
Right front			6 mm
Left rear			2 mm
Right rear			2 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors		✓	
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____