


Make:	Volkswagen	Model:	Golf
Body Style:	Wagon	Year:	2009
Rego No.:	MNZ593	Rego Expiry:	17 May 2026
WoF Expiry:	19 Sep 2026	Odometer:	145,217 Kms
Good No.:	28163241	VIN:	WVWZZZ1KZ8M366442
Next Service:	144000	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

- Left wing mirror housing and indicator damaged
- Worn front tires
- Front grille damaged
- Left taillight damaged

Conditions During Body Inspection	Dry
-----------------------------------	-----

### Under Carriage and Under Bonnet Inspection Comments

- Underbody surface rust
- Engine oil seepage

### Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Poor

### General Comments

- Low engine oil and coolant levels
- Fog lights not working
- Airbag light displayed
- Driver door is damaged, window wont close properly

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Unknown
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms
Inspected by:	Sione Mae
Published by:	Sione Mae
Inspection Date:	05 May 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition		✓	
Cooling performance		✓	
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			1 mm
Right front			3 mm
Left rear			3 mm
Right rear			4 mm
Spare		No	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_