

Report ID:	28,168,426	Version:	2
Created:	07 May 2026		


Make:	Mitsubishi	Model:	Delica
Body Style:	Van	Year:	2002
Rego No.:	FZN930	Rego Expiry:	13 Jul 2026
WoF Expiry:	17 Feb 2027	Odometer:	222,586 Kms
Good No.:	28168426	VIN:	7AT0CJ0PX11300046
Next Service:	229,000kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

L/R sliding door not opening.  
 Reversing mirror broken off.  
 Rust spots around R/R window.  
 Surface rust spots on roof.

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

Light surface rust under carriage.  
 Engine oil leaks.

**Interior Comments**

Seats:	Drivers seat ripped .
Carpets:	Holes & rips on drivers side.
Panels:	Scratches & scuffs in cargo area.
Dashboard:	Steering wheel worn.

**General Comments**

5 speed manual petrol van.  
 Radio not working.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    219,161 Kms
Inspected by:	Daryll Timms
Published by:	Leon Sun
Inspection Date:	07 May 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			4.0 mm
Right front			7.0 mm
Left rear			2.0 mm
Right rear			3.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_