

Report ID:	28,170,667	Version:	1
Created:	13 May 2026		


Make:	Ford	Model:	Transit
Body Style:	Van	Year:	2002
Rego No.:	CAK717	Rego Expiry:	27 Jul 2026
WoF Expiry:	20 Oct 2026	Odometer:	287,034 Kms
Good No.:	28170667	VIN:	WFOLXXGBFL1E21881
Next Service:	296,823kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

12 seater ( LVV for extra 10 seats in rear ). Major crack on side wall of left rear tyre. Right A-pillar is rusty. Decals and glues left around body. Left door mirror glass is delaminated. Dent in right sill under front door. Rear end window glassed cannot be closed properly.

Conditions During Body Inspection: **Dry**

### Under Carriage and Under Bonnet Inspection Comments

Leaking from rear differential and transmission, engine oil pan. Minor surface rust is developing under body.

### Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

### General Comments

Left front seat adjuster handle is missing. Main control switch of radio is faulty (no sound from left intermittently). Right tail light is not operating ( water inside) . Air fan control switch is broken. Right front air vent is broken.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Cambelt		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Kms
Inspected by:	Yuki Itohara		
Published by:	Tiaan Pienaar		
Inspection Date:	12 May 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			8.5 mm
Right front			8.5 mm
Left rear			0.0 mm
Right rear			6.0 mm
Spare		N/A	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation			✓
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors		✓	
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_