

Report ID:	28,181,789	Version:	1
Created:	15 May 2026		


Make:	Toyota	Model:	BB
Body Style:	Hatchback	Year:	2005
Rego No.:	JUY263	Rego Expiry:	01 Jul 2026
WoF Expiry:	04 Oct 2026	Odometer:	310,527 Kms
Good No.:	28181789	VIN:	7AT0H641X16095884
Next Service:	319905	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5.0 mm
Right front			5.1 mm
Left rear			1.7 mm
Right rear			3.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation		✓	
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR		✓	
Window winder RL		✓	
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

<b>Body Inspection Comments</b>	
Conditions During Body Inspection	Dry
<b>Under Carriage and Under Bonnet Inspection Comments</b>	
Front wheel drive	
Oil leak	
<b>Interior Comments</b>	
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good
<b>General Comments</b>	
Rear left window not working	
Front right window freezes when moving up or down and have to wait for it to move again	
Every time a door opens hazard lights turn on	
Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms
Inspected by:	Janine Bell
Published by:	Jaykib Collins
Inspection Date:	13 May 2026

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_