

Report ID:	28,182,517	Version:	1
Created:	18 May 2026		


Make:	Nissan	Model:	Navara
Body Style:	Utility	Year:	2009
Rego No.:	FCD786	Rego Expiry:	08 Sep 2026
WoF Expiry:	07 Jan 2027	Odometer:	336,064 Kms
Good No.:	28182517	VIN:	MNTCPUD22A0001039
Next Service:		Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Driver door hinges worn out. All tires are scalloped.
 Paintwork faded, clear coat coming off.
 Stone chips, dents, scratches, scuffs all over

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Driver side battery failed.
 Significant oil leak

Interior Comments

Seats:	marks
Carpets:	Average
Panels:	scratches scuffs marks drivers big dent
Dashboard:	Average

General Comments

Air conditioning/heating fan only works on full speed.
 Left front park light nor working
 Audible loud noise from engine when cold

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Gary Adams	
Published by:	Laura Iovine	
Inspection Date:	14 May 2026	

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			4.0 mm
Right front			5.0 mm
Left rear			6.0 mm
Right rear			5.0 mm
Spare		N/A	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights		✓	
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____