

Report ID:	28,191,323	Version:	1
Created:	18 May 2026		


Make:	Honda	Model:	Odyssey
Body Style:	People Mover	Year:	2005
Rego No.:	CLM417	Rego Expiry:	07 Jun 2026
WoF Expiry:	28 May 2026	Odometer:	268,493 Kms
Good No.:	28191323	VIN:	JHMRB18404C204702
Next Service:	Over due	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

- FL rear view mirror cover scratches
- RL door and boot interior seal torn
- Room lamp not glowing
- RR tail lamp cracked

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

- Fwd
- Engine oil leak
- Underbody surface rust
- FL sun visor needs refit

**Interior Comments**

Seats:	Good
Carpets:	Good
Panels:	Tailgate interior trim cracked
Dashboard:	Good

**General Comments**

- FL low beam headlight not glowing
- RR tyre inner edge worn
- Infotainment screen not turning on
- After market holes in roof hood lining

Road Conditions During Test Drive	Dry
-----------------------------------	-----

Engine Timing Mechanism	Timing Chain
-------------------------	--------------

Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
----------------------------------	--	-----

Inspected by:	Vasanthakumar Mayilswamy
---------------	--------------------------

Published by:	Vasanthakumar Mayilswamy
---------------	--------------------------

Inspection Date:	18 May 2026
------------------	-------------

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5 mm
Right front			5 mm
Left rear			4 mm
Right rear			4 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights		✓	
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL		✓	
Window winder FR		✓	
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_