

Report ID:	28,191,876	Version:	4
Created:	26 May 2026		


Make:	Volkswagen	Model:	Amarok
Body Style:	Utility	Year:	2015
Rego No.:	QLU518	Rego Expiry:	05 Nov 2026
WoF Expiry:	04 Jun 2027	Odometer:	282,715 Kms
Good No.:	28191876	VIN:	WV1ZZZ2HZFA016520
Next Service:	291,000 kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Front bumper moulding missing, dents and scrapes in bull bar  
 Chips in windscreen, dents rear cab panel, tears in tonneau cover  
 Dent right cab corner,  
 Right running board moulding missing,

Conditions During Body Inspection    Dry

**Under Carriage and Under Bonnet Inspection Comments**

**Interior Comments**

Seats:	right front seat base torn
Carpets:	holes right front carpet
Panels:	Average
Dashboard:	holes in dash

**General Comments**

Right front grab handle needs refitted , steering wheel worn  
 One key broken, other remote not found by vehicle  
 Parking sensors and park assist not working

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    270,000 Kms
Inspected by:	Dean Sinclair
Published by:	Shane Charlton
Inspection Date:	18 May 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			12.0 mm
Right front			12.0 mm
Left rear			12.0 mm
Right rear			12.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)		✓	
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_