

Report ID:	28,193,527	Version:	2
Created:	19 May 2026		


Make:	Isuzu	Model:	Bighorn
Body Style:	Wagon	Year:	1998
Rego No.:	KRL748	Rego Expiry:	25 Aug 2026
WoF Expiry:	26 Jul 2026	Odometer:	185,402 Kms
Good No.:	28193527	VIN:	7A897130707203378
Next Service:	194,418	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Sunroof taped up on roof-

Conditions During Body Inspection

Dry

Under Carriage and Under Bonnet Inspection Comments

4wd
 Left outer cv boot spilt, Rear diff oil seepage
 Rear axle seal oil seepage, Underbody surface rust

Interior Comments

Seats:	adjustment leave missing on front passenger seat
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Black Smoke when accelerating,
 Third row seats missing, A little hard to start when cold
 Sunroof doesn't work
 Radio has constant power remove radio face to turn off

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Kms

Inspected by:	Kyle Kelly
Published by:	Miroslav Granich
Inspection Date:	19 May 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes		✓	
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			6.8 mm
Right front			7.2 mm
Left rear			7.0 mm
Right rear			6.8 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys		2	
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____