

Report ID:	28,206,817	Version:	1
Created:	26 May 2026		


Make:	Ford	Model:	Mondeo
Body Style:	Sedan	Year:	2011
Rego No.:	FYC106	Rego Expiry:	09 Mar 2027
WoF Expiry:	03 Oct 2026	Odometer:	200,560 Kms
Good No.:	28206817	VIN:	WF0DXXGBBDAS72057
Next Service:	208,600km	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Left & right sill panels are dented. Left taillight is broken.  
 RF mudflap is loosely cable tied in place.

Conditions During Body Inspection: Wet

### Under Carriage and Under Bonnet Inspection Comments

Some underbody surface rust.

### Interior Comments

Seats:	Good, LR seatbelt webbing is damaged.
Carpets:	Good
Panels:	Good
Dashboard:	Good

### General Comments

Dash display doesn't work, unable to see how many kilometres vehicle has travelled.

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms
Inspected by:	Blair Robertson
Published by:	Blair Robertson
Inspection Date:	26 May 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5.5 mm
Right front			5.5 mm
Left rear			4.5 mm
Right rear			4 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_