

Report ID:	28,218,656	Version:	3
Created:	02 Jun 2026		


Make:	Mazda	Model:	CX-5
Body Style:	SUV	Year:	2018
Rego No.:	LHK416	Rego Expiry:	17 Nov 2026
WoF Expiry:	10 Jun 2027	Odometer:	174,373 Kms
Good No.:	28218656	VIN:	JM0KF4WLA00152999
Next Service:	174,200 Kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

WOF expires 10/6/27
 RH side mirror mount cracked. Seal between RF and RR doors torn.
 Tyre iron missing.
 LR inner wheel arch/door jam panel dented and scratched.

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Average, drivers seat base worn.
Carpets:	Good. Rear floor mats missing.
Panels:	Average. Drivers side centre console panel missing
Dashboard:	Average, steering wheel worn.

General Comments

Minor damage to RR seatbelt webbing. Service past due message on dash.
 Instrument cluster cracked.
 Rear window wiper needs replaced.
 Top of key remote damaged.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Lewis Dolamore		
Published by:	Kate Gibson		
Inspection Date:	29 May 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			7.5 mm
Right front			7.5 mm
Left rear			7.5 mm
Right rear			7.5 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)		✓	
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____