

Report ID:	28,226,607	Version:	1
Created:	04 Jun 2026		


Make:	Mitsubishi	Model:	Pajero Sport
Body Style:	SUV	Year:	2022
Rego No.:	PGW506	Rego Expiry:	12 May 2026
WoF Expiry:	05 Feb 2027	Odometer:	62,988 Kms
Good No.:	28226607	VIN:	MMAGUKS10NH006150
Next Service:	30,854 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

RH front bumper moulding fits poorly. LH running board damaged.
RF, LF, and tailgate door seals torn.
Spare wheel missing.
LR inner wheel arch damaged.

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

No coolant in coolant reservoir.

Interior Comments

Seats: Poor, drivers seat base torn.
Carpets: Average
Panels: Average
Dashboard: Average, steering wheel worn.

General Comments

Rear parking sensors beep continuously when reversing.
Front window washers need adjusted. Airbag/SRS warning light on.
Radio touch screen not working.
Second row RH seat back unzipped and foam torn.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Troy Smith		
Published by:	Troy Smith		
Inspection Date:	04 Jun 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			2 mm
Right front			4.5 mm
Left rear			3.5 mm
Right rear			2.5 mm
Spare		No	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____