


| | | | |
|------------|-------------|----------|---|
| Report ID: | 28,232,671 | Version: | 1 |
| Created: | 08 Jun 2026 | | |

| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Nissan | Model: | Regulus |
| Body Style: | Wagon | Year: | 1997 |
| Rego No.: | BHF294 | Rego Expiry: | 09 Jul 2026 |
| WoF Expiry: | 28 Aug 2026 | Odometer: | 286,450 Kms |
| Good No.: | 28232671 | VIN: | 7A8DH5K0703007511 |
| Next Service: | 292,897 Kms | Service History: | No |

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both running boards scuffed. Wiper arms need repainted.
 LF door window monsoon damaged.
 LH side mirror scuffed.
 Front bumper zip tied on LH side.

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Engine oil leak.
 Minor undercarriage surface rust.
 Surface rust on radiator support.

Interior Comments

| | |
|------------|----------------------------------|
| Seats: | Average, drivers seat base worn. |
| Carpets: | Average, missing floor mats. |
| Panels: | Average |
| Dashboard: | Good |

General Comments

Rear wiper blade needs replaced.
 HVAC vent mode selector not working, air only coming from floor vent.
 AC not cold.
 Tachometer not working. Dash cluster gear position light for Drive not working.

| | | | |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry | | |
| Engine Timing Mechanism | Timing Chain | | |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by: | Troy Smith | | |
| Published by: | Troy Smith | | |
| Inspection Date: | 08 Jun 2026 | | |

| | OK | Requires Attention | N/A |
|---|----|--------------------|--------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | | 6.5 mm |
| Right front | | | 6.5 mm |
| Left rear | | | 5.5 mm |
| Right rear | | | 5 mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | | ✓ | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 3 | | |
| Central locking | ✓ | | |
| Remote locking | | | ✓ |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____