

Report ID:	28,237,244	Version:	1
Created:	10 Jun 2026		


Make:	Nissan	Model:	Tiida
Body Style:	Hatchback	Year:	2005
Rego No.:	LRW104	Rego Expiry:	08 Apr 2027
WoF Expiry:	07 Mar 2027	Odometer:	115,104 Kms
Good No.:	28237244	VIN:	7AT0DH78X18039469
Next Service:	121,000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

- Right wing mirror housing damage
- Rear bumper misaligned
- Left wing mirror housing scuff
- Left side skirt scuff

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

- Subframe surface rust
- Underbody oxidation
- Front left tyre outer edge wear
- Rear right tyre worn

Interior Comments

Seats:	torn
Carpets:	Good
Panels:	Good
Dashboard:	middle console ripped

General Comments

- Suspected worn suspension (Requires further investigation)
- Noisy drive belt
- No volume from radio

Road Conditions During Test Drive	Dry
-----------------------------------	-----

Engine Timing Mechanism	Timing Chain
-------------------------	--------------

Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
----------------------------------	--	-----

Inspected by:	Kilipati Mae
---------------	--------------

Published by:	Kilipati Mae
---------------	--------------

Inspection Date:	10 Jun 2026
------------------	-------------

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			4 mm
Right front			3 mm
Left rear			4 mm
Right rear			1 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____