


Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2020
Rego No.:	QNK500	Rego Expiry:	14 Nov 2025
WoF Expiry:	08 Apr 2026	Odometer:	108,798 Kms
Good No.:	28252529	VIN:	MPBUMFF60LX308866
Next Service:	99000	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Windscreen crack outside cva, RB crack ,L cab cover and quarter panel impact damage. LR flair unsecure ,L running board damage .

Under Carriage and Under Bonnet Inspection Comments

Underbody surface rust.

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Service overdue .

	OK	Requires Attention	N/A
Engine			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	16 mm		
Right front	16 mm		
Left rear	14 mm		
Right rear	14 mm		
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

SIGNATURE