


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | LDV         | Model:           | V80               |
| Body Style:   | Minibus     | Year:            | 2020              |
| Rego No.:     | MQF69       | Rego Expiry:     | 28 Jul 2026       |
| WoF Expiry:   | 18 Sep 2026 | Odometer:        | 59,470 Kms        |
| Good No.:     | 28257340    | VIN:             | LSKG5GL12KA096928 |
| Next Service: | 72,100 kms  | Service History: | Yes               |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Carpet torn, left front guard plastic cover missing, second row seat torn and left side seat belt twisted, left sliding doorstep plate not closing faulty, exterior body rust,

Conditions During Body Inspection

Wet

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

|            |         |
|------------|---------|
| Seats:     | Average |
| Carpets:   | Average |
| Panels:    | Average |
| Dashboard: | Good    |

## General Comments

Driver door noise when open, left sliding door can't open, windscreen cracked out cva, hand brake too high, inter roof light glass missing,

|                                   |                                                              |
|-----------------------------------|--------------------------------------------------------------|
| Road Conditions During Test Drive | Wet                                                          |
| Engine Timing Mechanism           | Timing Chain                                                 |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No Kms |
| Inspected by:                     | Marlon Espena                                                |
| Published by:                     | Henry Manders                                                |
| Inspection Date:                  | 17 Jun 2026                                                  |

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 28,257,340  | Version: | 4 |
| Created:   | 16 Jul 2026 |          |   |

|                                                     | OK | Requires Attention | N/A    |
|-----------------------------------------------------|----|--------------------|--------|
| <b>Engine</b>                                       |    |                    |        |
| Oil level                                           | ✓  |                    |        |
| Smoke & fumes                                       | ✓  |                    |        |
| Engine performance                                  | ✓  |                    |        |
| Noise                                               | ✓  |                    |        |
| Coolant condition                                   | ✓  |                    |        |
| Cooling performance                                 | ✓  |                    |        |
| Radiator / Hoses (visual)                           | ✓  |                    |        |
| <b>Transmission</b>                                 |    |                    |        |
| Operation                                           | ✓  |                    |        |
| Noise                                               | ✓  |                    |        |
| Clutch                                              |    |                    | ✓      |
| CV joints                                           | ✓  |                    |        |
| Wheel bearings                                      | ✓  |                    |        |
| <b>Brakes</b>                                       |    |                    |        |
| Performance                                         | ✓  |                    |        |
| Hand brake                                          | ✓  |                    |        |
| <b>Tyres (lowest observed tread depth of tyres)</b> |    |                    |        |
| Left front                                          |    |                    | 5.0 mm |
| Right front                                         |    |                    | 5.0 mm |
| Left rear                                           |    |                    | 3.0 mm |
| Right rear                                          |    |                    | 3.0 mm |
| Spare                                               |    | Yes                |        |
| <b>Suspension</b>                                   |    |                    |        |
| Suspension performance                              | ✓  |                    |        |
| Steering performance                                | ✓  |                    |        |
| Shock absorbers                                     | ✓  |                    |        |
| <b>Air Conditioning / Heater</b>                    |    |                    |        |
| Operation                                           | ✓  |                    |        |
| <b>Electrical / Accessories</b>                     |    |                    |        |
| Head lights                                         | ✓  |                    |        |
| Tail lights                                         | ✓  |                    |        |
| Indicators                                          | ✓  |                    |        |
| Dashboard warning lights                            | ✓  |                    |        |
| Wipers (front & rear)                               | ✓  |                    |        |
| Window winder FL                                    | ✓  |                    |        |
| Window winder FR                                    | ✓  |                    |        |
| Window winder RL                                    |    |                    | ✓      |
| Window winder RR                                    |    |                    | ✓      |
| Rear view mirrors                                   | ✓  |                    |        |
| Radio (basic test only)                             | ✓  |                    |        |
| CD (basic test only)                                |    |                    | ✓      |
| Number of keys                                      | 1  |                    |        |
| Central locking                                     | ✓  |                    |        |
| Remote locking                                      | ✓  |                    |        |
| Sat. nav. (basic test only)                         |    |                    | ✓      |
| Reversing camera                                    | ✓  |                    |        |