

Report ID:	28,258,721	Version:	1
Created:	03 Jul 2026		


Make:	Nissan	Model:	Fuga
Body Style:	Sedan	Year:	2007
Rego No.:	MUP91	Rego Expiry:	10 Jul 2026
WoF Expiry:	10 Jul 2027	Odometer:	155,723 Kms
Good No.:	28258721	VIN:	7AT0DH8GX19155480
Next Service:	165,721kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both side body kits are cracked and not fitted correctly. Right rear door chrome moulding is coming off. Paint is fading on roof bonnet doors. Battery cover trim is missing. Right front door seal rubber is worn, torn.

Conditions During Body Inspection: Dry

Under Carriage and Under Bonnet Inspection Comments

Weeping from engine and transmission.

Interior Comments

Seats:	Good
Carpets:	Average
Panels:	Roof lining is sagging badly.
Dashboard:	Surface is cracked badly.

General Comments

AC air vent for rear is broken. Centre console rear pocket is jammed. Front drink holder is broken. Rends of reverse camera is too cloudy to see.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Yuki Itohara	
Published by:	Callum Busuttill	
Inspection Date:	26 Jun 2026	

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			4.5 mm
Right front			5.0 mm
Left rear			4.0 mm
Right rear			4.0 mm
Spare		N/A	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera		✓	

I have read and understood this condition guide:

NAME _____

SIGNATURE _____