


| | | | |
|------------|-------------|----------|---|
| Report ID: | 28,261,367 | Version: | 1 |
| Created: | 17 Jun 2026 | | |

| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Toyota | Model: | Hiace |
| Body Style: | Van | Year: | 2014 |
| Rego No.: | MBW401 | Rego Expiry: | 03 Nov 2026 |
| WoF Expiry: | 29 May 2026 | Odometer: | 205,194 Kms |
| Good No.: | 28261367 | VIN: | 7AT0H60FX18148907 |
| Next Service: | 186,000 | Service History: | No |

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Rear tail gate body seal torn, spare tool missing, engine oil leak,

Conditions During Body Inspection

Wet

Under Carriage and Under Bonnet Inspection Comments

Service overdue

Interior Comments

| | |
|------------|---------|
| Seats: | Poor |
| Carpets: | Poor |
| Panels: | Poor |
| Dashboard: | Average |

General Comments

Front seat torn, window tent torn, air vent broken, windscreen cracked out cva, radio unsecured,

Road Conditions During Test Drive Wet

Engine Timing Mechanism Cambelt

Evidence of Cam Belt Replacement Yes No 204,000 Kms

Inspected by: Marlon Espena

Published by: Marlon Espena

Inspection Date: 17 Jun 2026

| | OK | Requires Attention | N/A |
|-----------------------------------------------------|----|--------------------|------|
| Engine | | | |
| Oil level | | ✓ | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | | ✓ | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | | 7 mm |
| Right front | | | 7 mm |
| Left rear | | | 3 mm |
| Right rear | | | 3 mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | | | ✓ |
| Window winder RR | | | ✓ |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | | | ✓ |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | ✓ | | |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____