

Report ID:	28,269,438	Version:	1
Created:	26 Jun 2026		


Make:	Nissan	Model:	Fuga
Body Style:	Sedan	Year:	2007
Rego No.:	HSZ37	Rego Expiry:	02 Mar 2027
WoF Expiry:	23 May 2027	Odometer:	132,344 Kms
Good No.:	28269438	VIN:	7AT0DH8GX14450744
Next Service:	129,064kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Service is overdue. Right front guard indicator cover is missing. Right fog light glass is broken. Edge of right tail light is cracked. Right front door check strap is worn. Jack and tools are missing.

Conditions During Body Inspection: Dry

### Under Carriage and Under Bonnet Inspection Comments

Weeping from left side of power steering rack out put boot.

### Interior Comments

Seats:	Side of right front base pad is worn.
Carpets:	Good
Panels:	Good
Dashboard:	Good

### General Comments

Remote key unlock button is faulty. Electric mirrors auto folding is not operating.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Yuki Itohara		
Published by:	Callum Busuttill		
Inspection Date:	23 Jun 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			6.0 mm
Right front			6.0 mm
Left rear			4.0 mm
Right rear			4.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_