


Report ID:	28,269,625	Version:	1
Created:	23 Jun 2026		

Make:	Nissan	Model:	Navara
Body Style:	Utility	Year:	2006
Rego No.:	DFB680	Rego Expiry:	31 Oct 2026
WoF Expiry:	03 Jun 2026	Odometer:	328,203 Kms
Good No.:	28269625	VIN:	VSKCVND40A0071643
Next Service:	330000	Service History:	No

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes		✓	
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance		✓	
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5.9 mm
Right front			5.8 mm
Left rear			5.4 mm
Right rear			6.2 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

Body Inspection Comments

Conditions During Body Inspection	Wet
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Four wheel drive
 Oil leak
 Front right CV leaking

Interior Comments

Seats:	Average
Carpets:	missing and damaged in drivers area
Panels:	Average
Dashboard:	Average

General Comments

Brakes soft
 squeals when turning at full lock
 Glovebox handle broken

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms

Inspected by:	Jesse Amey
Published by:	Janine Bell
Inspection Date:	21 Jun 2026

I have read and understood this condition guide:

NAME _____

SIGNATURE _____