

Report ID:	28,271,464	Version:	3
Created:	22 Jun 2026		


Make:	Mitsubishi	Model:	RVR
Body Style:	SUV	Year:	2014
Rego No.:	MQN549	Rego Expiry:	01 May 2026
WoF Expiry:	08 Apr 2026	Odometer:	188,600 Kms
Good No.:	28271464	VIN:	7AT0CJ1KX19400486
Next Service:	198,000 Kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Front bumper lower grille cracked.  
 RF sill step plate worn.

Conditions During Body Inspection

**Under Carriage and Under Bonnet Inspection Comments**

Front engine undertray cracked.

**Interior Comments**

Seats:	Average, drivers seat base torn.
Carpets:	Good
Panels:	Average, headliner stained. Drivers sunvisor loose.
Dashboard:	Average, steering wheel worn.

**General Comments**

Routine maintenance required message on dash. Steering pulls to the left.  
 Brake pulsation in driveline when braking. Engine rattle on cold start up.  
 Auto stop&go light flashing.  
 AC not cold. Rear window wiper blade needs replaced.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Troy Smith	
Published by:	Pieter Van Vliet	
Inspection Date:	22 Jun 2026	

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			2.0 mm
Right front			2.5 mm
Left rear			2.0 mm
Right rear			3.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation		✓	
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_