

Report ID:	28,277,036	Version:	1
Created:	27 Jun 2026		


Make:	Mazda	Model:	Axela
Body Style:	Hatchback	Year:	2007
Rego No.:	RWF630	Rego Expiry:	23 Aug 2026
WoF Expiry:	11 Jun 2027	Odometer:	208,508 Kms
Good No.:	28277036	VIN:	7AT0C13JX13306399
Next Service:		Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Screws drilled into front bumper on left side
 Screws drilled into both sides of rear bumper
 Inside of boot wet spots of corrosion starting
 Right side side skirt damaged

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Front wheel drive

Interior Comments

Seats:	cracks
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Due for service
 Vibration on startups and when driving suspected top engine mount worn
 Right rear window jamming/ gets stuck

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Jesse Amey
Published by:	Jaykib Collins
Inspection Date:	24 Jun 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			3.3 mm
Right front			3.2 mm
Left rear			2.6 mm
Right rear			6.4 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR		✓	
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____