

Report ID:	28,282,052	Version:	1
Created:	29 Jun 2026		


Make:	Subaru	Model:	Impreza
Body Style:	Hatchback	Year:	2012
Rego No.:	MUW413	Rego Expiry:	01 Dec 2026
WoF Expiry:	18 Jun 2027	Odometer:	170,141 Kms
Good No.:	28282052	VIN:	7AT0GF1XX19021161
Next Service:	no record	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Roof rack key is missing. Left door mirror is missing bottom cover. Paint stained all over the body panels. Factory Run-Flat kit Seal liquid is empty.

Conditions During Body Inspection: Dry

Under Carriage and Under Bonnet Inspection Comments

Leaking from engine. Major leaking from transmission. Front suspension lower arm bushes are perishing. Left sill rip has bent.

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Fuse Lid clips are missing, under start button.

General Comments

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Yuki Itohara		
Published by:	Callum Busuttill		
Inspection Date:	25 Jun 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			2.5 mm
Right front			3.5 mm
Left rear			5.5 mm
Right rear			4.0 mm
Spare		N/A	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____