

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 28,295,126  | Version: | 3 |
| Created:   | 21 Jul 2026 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | MG          | Model:           | HS                |
| Body Style:   | SUV         | Year:            | 2020              |
| Rego No.:     | RTW744      | Rego Expiry:     | 12 Feb 2027       |
| WoF Expiry:   | 22 Jul 2027 | Odometer:        | 126,807 Kms       |
| Good No.:     | 28295126    | VIN:             | LSJA24U95LN017705 |
| Next Service: | 133,000     | Service History: | Yes               |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Spider rust on roof.

|                                   |     |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

### Under Carriage and Under Bonnet Inspection Comments

## Oil seepage

### Interior Comments

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

## General Comments

## Steering wheel stitching come away

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Kilipati Mae                 |                             |     |
| Published by:                     | Tim Jones                    |                             |     |
| Inspection Date:                  | 04 Jul 2026                  |                             |     |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

|                                                     | OK  | Requires<br>Attention | N/A    |
|-----------------------------------------------------|-----|-----------------------|--------|
| <b>Engine</b>                                       |     |                       |        |
| Oil level                                           | ✓   |                       |        |
| Smoke & fumes                                       | ✓   |                       |        |
| Engine performance                                  | ✓   |                       |        |
| Noise                                               | ✓   |                       |        |
| Coolant condition                                   | ✓   |                       |        |
| Cooling performance                                 | ✓   |                       |        |
| Radiator / Hoses (visual)                           | ✓   |                       |        |
| <b>Transmission</b>                                 |     |                       |        |
| Operation                                           | ✓   |                       |        |
| Noise                                               | ✓   |                       |        |
| Clutch                                              |     |                       | ✓      |
| CV joints                                           | ✓   |                       |        |
| Wheel bearings                                      | ✓   |                       |        |
| <b>Brakes</b>                                       |     |                       |        |
| Performance                                         | ✓   |                       |        |
| Hand brake                                          | ✓   |                       |        |
| <b>Tyres</b> (lowest observed tread depth of tyres) |     |                       |        |
| Left front                                          |     |                       | 5.0 mm |
| Right front                                         |     |                       | 6.0 mm |
| Left rear                                           |     |                       | 6.0 mm |
| Right rear                                          |     |                       | 6.0 mm |
| Spare                                               | Yes |                       |        |
| <b>Suspension</b>                                   |     |                       |        |
| Suspension performance                              | ✓   |                       |        |
| Steering performance                                | ✓   |                       |        |
| Shock absorbers                                     | ✓   |                       |        |
| <b>Air Conditioning / Heater</b>                    |     |                       |        |
| Operation                                           | ✓   |                       |        |
| <b>Electrical / Accessories</b>                     |     |                       |        |
| Head lights                                         | ✓   |                       |        |
| Tail lights                                         | ✓   |                       |        |
| Indicators                                          | ✓   |                       |        |
| Dashboard warning lights                            | ✓   |                       |        |
| Wipers (front & rear)                               | ✓   |                       |        |
| Window winder FL                                    | ✓   |                       |        |
| Window winder FR                                    | ✓   |                       |        |
| Window winder RL                                    | ✓   |                       |        |
| Window winder RR                                    | ✓   |                       |        |
| Rear view mirrors                                   | ✓   |                       |        |
| Radio (basic test only)                             | ✓   |                       |        |
| CD (basic test only)                                |     |                       | ✓      |
| Number of keys                                      | 2   |                       |        |
| Central locking                                     | ✓   |                       |        |
| Remote locking                                      | ✓   |                       |        |
| Sat. nav. (basic test only)                         | ✓   |                       |        |
| Reversing camera                                    | ✓   |                       |        |