

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 28,295,721  | Version: | 1 |
| Created:   | 02 Jul 2026 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Toyota      | Model:           | Landcruiser Prado |
| Body Style:   | SUV         | Year:            | 2010              |
| Rego No.:     | FJB804      | Rego Expiry:     | 17 Sep 2026       |
| WoF Expiry:   | 27 Aug 2026 | Odometer:        | 451,930 Kms       |
| Good No.:     | 28295721    | VIN:             | JTEBH3FJ90K016667 |
| Next Service: | 440918      | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

### Minor stonechips on windscreen

|                                   |     |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

### Under Carriage and Under Bonnet Inspection Comments

Four wheel drive  
Oil leak Rust hole  
Transmission leak  
Bash plate/skid plate rusty

### Interior Comments

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

### General Comments

Due for service  
Hood struts need re gassing or replacement

|                                   |                                         |                             |             |
|-----------------------------------|-----------------------------------------|-----------------------------|-------------|
| Road Conditions During Test Drive | Dry                                     |                             |             |
| Engine Timing Mechanism           | Cambelt                                 |                             |             |
| Evidence of Cam Belt Replacement  | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | 409,367 Kms |
| Inspected by:                     | Jesse Amey                              |                             |             |
| Published by:                     | Jesse Amey                              |                             |             |
| Inspection Date:                  | 02 Jul 2026                             |                             |             |

|                                              | OK     | Requires<br>Attention | N/A |
|----------------------------------------------|--------|-----------------------|-----|
| Engine                                       |        |                       |     |
| Oil level                                    | ✓      |                       |     |
| Smoke & fumes                                | ✓      |                       |     |
| Engine performance                           | ✓      |                       |     |
| Noise                                        | ✓      |                       |     |
| Coolant condition                            | ✓      |                       |     |
| Cooling performance                          | ✓      |                       |     |
| Radiator / Hoses (visual)                    | ✓      |                       |     |
| Transmission                                 |        |                       |     |
| Operation                                    | ✓      |                       |     |
| Noise                                        | ✓      |                       |     |
| Clutch                                       |        |                       | ✓   |
| CV joints                                    | ✓      |                       |     |
| Wheel bearings                               | ✓      |                       |     |
| Brakes                                       |        |                       |     |
| Performance                                  | ✓      |                       |     |
| Hand brake                                   | ✓      |                       |     |
| Tyres (lowest observed tread depth of tyres) |        |                       |     |
| Left front                                   | 7.4 mm |                       |     |
| Right front                                  | 7 mm   |                       |     |
| Left rear                                    | 9 mm   |                       |     |
| Right rear                                   | 9.2 mm |                       |     |
| Spare                                        | Yes    |                       |     |
| Suspension                                   |        |                       |     |
| Suspension performance                       | ✓      |                       |     |
| Steering performance                         | ✓      |                       |     |
| Shock absorbers                              | ✓      |                       |     |
| Air Conditioning / Heater                    |        |                       |     |
| Operation                                    | ✓      |                       |     |
| Electrical / Accessories                     |        |                       |     |
| Head lights                                  | ✓      |                       |     |
| Tail lights                                  | ✓      |                       |     |
| Indicators                                   | ✓      |                       |     |
| Dashboard warning lights                     | ✓      |                       |     |
| Wipers (front & rear)                        | ✓      |                       |     |
| Window winder FL                             | ✓      |                       |     |
| Window winder FR                             | ✓      |                       |     |
| Window winder RL                             | ✓      |                       |     |
| Window winder RR                             | ✓      |                       |     |
| Rear view mirrors                            | ✓      |                       |     |
| Radio (basic test only)                      | ✓      |                       |     |
| CD (basic test only)                         | ✓      |                       |     |
| Number of keys                               | 2      |                       |     |
| Central locking                              | ✓      |                       |     |
| Remote locking                               | ✓      |                       |     |
| Sat. nav. (basic test only)                  |        |                       | ✓   |
| Reversing camera                             | ✓      |                       |     |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

**SIGNATURE**