


Report ID:	28,297,520	Version:	1
Created:	02 Jul 2026		

Make:	Hyundai	Model:	Santa FE
Body Style:	SUV	Year:	2013
Rego No.:	HEF599	Rego Expiry:	14 Jul 2026
WoF Expiry:	19 Aug 2026	Odometer:	347,255 Kms
Good No.:	28297520	VIN:	KMHST81XSEU229247
Next Service:	338,000kms	Service History:	Yes

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Right cant rail dented at rear.  
 Paint peeling off spoiler.  
 Windscreen cracked, replacement needed.

Conditions During Body Inspection    Wet

### Under Carriage and Under Bonnet Inspection Comments

Engine oil leaks.

### Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

### General Comments

Service history to 2017 only.  
 Service overdue.  
 Knock in steering, suggest further investigation.  
 AWD diesel auto SUV.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms

Inspected by:	Daryll Timms
Published by:	Daryll Timms
Inspection Date:	02 Jul 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5 mm
Right front			6 mm
Left rear			7 mm
Right rear			7 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance		✓	
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:    **NAME** \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_