


Make:	Hyundai	Model:	Iload
Body Style:	Van	Year:	2019
Rego No.:	MDW153	Rego Expiry:	31 Aug 2026
WoF Expiry:	06 Jul 2027	Odometer:	170,465 Kms
Good No.:	28313760	VIN:	KMFWBX7KMLU083161
Next Service:	180,000kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Tailgate lock damaged.
R/r interior step plate cracked.

Under Carriage and Under Bonnet Inspection Comments

Seats:	Good
Carpets:	Good
Panels:	Poor
Dashboard:	Good

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	LukaAjitvan Woerden		
Published by:	LukaAjitvan Woerden		
Inspection Date:	11 Jul 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____