

Report ID:	28,314,206	Version:	2
Created:	13 Jul 2026		


Make:	Mazda	Model:	CX-5
Body Style:	SUV	Year:	2023
Rego No.:	QBZ9	Rego Expiry:	27 Aug 2026
WoF Expiry:	28 Feb 2027	Odometer:	85,224 Kms
Good No.:	28314206	VIN:	JM0KF2W7A10861119
Next Service:	91,000 kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper r side valance damage

Conditions During Body Inspection

Wet

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

One key blade missing,windscreen cracked major, passenger sun visor missing plastic cover,

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	☐ Yes ☐ No Kms
Inspected by:	Marlon Espena
Published by:	Darryl Kereti
Inspection Date:	09 Jul 2026

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes</			