


Make:	Ford	Model:	Focus
Body Style:	Sedan	Year:	2012
Rego No.:	GPC44	Rego Expiry:	12 Jan 2027
WoF Expiry:	11 Oct 2026	Odometer:	150,759 Kms
Good No.:	28318745	VIN:	MPB2XXMXB2CY14474
Next Service:	157769 kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Headlights fading. Left taillight has crack. LF seatbelt beginning to fray.

Conditions During Body Inspection

Wet

Under Carriage and Under Bonnet Inspection Comments

Engine oil stains. Rear subframe surface rust. LF tyre sidewall minor damage.

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Good

General Comments

Engine misfire felt at idle. Service due by date. Steering column trim piece missing. Light switch surround trim missing. Steering wheel and gear knob worn. Key battery low warning on dash. Water noise from behind dash.

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	☐ Yes ☐ No Kms
Inspected by:	Eleoit Kumar
Published by:	Eleoit Kumar
Inspection Date:	14 Jul 2026

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____

Report ID:	28,318,745	Version:	1
Created:	14 Jul 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5 mm
Right front			5 mm
Left rear			6 mm
Right rear			6 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		