


Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

General Comments

Has EV charger

Road Conditions During Test Drive		Wet	
Engine Timing Mechanism		Unknown	
Evidence of Cam Belt Replacement		☐ Yes	☐ No
Inspected by:	Curshey Accad		
Published by:	Syariah Saemo		
Inspection Date:	14 Jul 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____

Transmission			
Operation			✓
Noise			✓
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake			✓
Tyres (lowest observed tread depth of tyres)			
Left front	6.0 mm		
Right front	6.0 mm		
Left rear	5.0 mm		
Right rear	5.0 mm		
Spare	N/A		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)	✓		
Reversing camera	✓		