


Make:	Ford	Model:	Fiesta
Body Style:	Hatchback	Year:	2013
Rego No.:	HDY361	Rego Expiry:	20 May 2027
WoF Expiry:	17 Jun 2026	Odometer:	101,323 Kms
Good No.:	28323573	VIN:	MNB8XXARJ8DC17548
Next Service:	Overdue	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Windscreen stone chips.

Under Carriage and Under Bonnet Inspection Comments

Right front inner CV boot leaking.

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

I have read and understood
this condition guide:

NAME _____

SIGNATURE

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	4.3 mm		
Right front	3.9 mm		
Left rear	2.2 mm		
Right rear	3.6 mm		
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓