


Make:	Mini	Model:	Clubman Cooper
Body Style:	Hatchback	Year:	2009
Rego No.:	KFH527	Rego Expiry:	27 Aug 2026
WoF Expiry:	25 Nov 2026	Odometer:	195,336 Kms
Good No.:	28340513	VIN:	WMWML32000TM96811
Next Service:	205,150km	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Windscreen stone chips

Engine oil leaks
Front wheel drive

Seats:	Good
Carpets:	Average
Panels:	Good
Dashboard:	Good

General Comments

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		☐ Yes	☐ No
Inspected by:		Rowan Fey	
Published by:		Rowan Fey	
Inspection Date:		23 Jul 2026	

NAME _____

SIGNATURE _____