

Report ID:	28,357,304	Version:	1
Created:	29 Jul 2026		


Make:	Hyundai	Model:	Iload
Body Style:	Van	Year:	2020
Rego No.:	MQS958	Rego Expiry:	22 Nov 2026
WoF Expiry:	11 Mar 2027	Odometer:	100,485 Kms
Good No.:	28357304	VIN:	KMFWBX7KMLU101024
Next Service:	102000 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left sill badly dented. LOAD badge missing letters.
Rear left roof rack mount torn off other 3 corner mounts cracked.
Minor stone chip in windscreen. Green paint on right rear door.
Rear bumper and tail gate stained with paint. Rear bumper reflector missing.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Average
Carpets:	Poor
Panels:	Poor
Dashboard:	Average

General Comments

2WD. Tail gate seal torn.
Centre interior tail gate step trim broken and cracked.
Left rear door interior step trim cracked. Cargo area full of paint stains
Left front door card stained with paint.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	☐ Yes ☐ No Kms
Inspected by:	Flynn Burdon
Published by:	Malcolm Thomas
Inspection Date:	29 Jul 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			7.5 mm
Right front			7.5 mm
Left rear			4.0 mm
Right rear			4.5 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____