


Make:	Nissan	Model:	Navara
Body Style:	Utility	Year:	2019
Rego No.:	MBA272	Rego Expiry:	26 Sep 2026
WoF Expiry:	02 May 2026	Odometer:	123,034 Kms
Good No.:	28363419	VIN:	MNTCB2D23A0014259
Next Service:	132500	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



No roof rack key
Both rear door seals damaged

Rear wheel drive

Seats:	Good
Carpets:	Good
Panels:	Minor scratches, Good
Dashboard:	Good

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		☐ Yes	☐ No
Inspected by:	Jaykib Collins		
Published by:	Jaykib Collins		
Inspection Date:	06 Aug 2026		

SIGNATURE