

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Front tyres inner edge wear/

2WD/transmission leak/minor underbody surface rust/

Dashboard:	Average
------------	---------

Inspection Date:	04 Aug 2026
------------------	-------------

SIGNATURE