

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 28,374,499  | Version: | 1 |
| Created:   | 11 Aug 2026 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Suzuki      | Model:           | Vitara            |
| Body Style:   | SUV         | Year:            | 2021              |
| Rego No.:     | NLW276      | Rego Expiry:     | 01 Dec 2026       |
| WoF Expiry:   | 02 Jun 2027 | Odometer:        | 85,486 Kms        |
| Good No.:     | 28374499    | VIN:             | TSMLYDA1S00871858 |
| Next Service: | 95,000 Kms  | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Conditions During Body Inspection Dry

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

|            |         |
|------------|---------|
| Seats:     | Average |
| Carpets:   | Average |
| Panels:    | Good    |
| Dashboard: | Good    |

## General Comments

|                                   |                              |                             |     |
|-----------------------------------|------------------------------|-----------------------------|-----|
| Road Conditions During Test Drive | Dry                          |                             |     |
| Engine Timing Mechanism           | Timing Chain                 |                             |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes | <input type="checkbox"/> No | Kms |
| Inspected by:                     | Kees Gould                   |                             |     |
| Published by:                     | Grant Markham                |                             |     |
| Inspection Date:                  | 05 Aug 2026                  |                             |     |

|                                              | OK     | Requires<br>Attention | N/A |
|----------------------------------------------|--------|-----------------------|-----|
| Engine                                       |        |                       |     |
| Oil level                                    | ✓      |                       |     |
| Smoke & fumes                                | ✓      |                       |     |
| Engine performance                           | ✓      |                       |     |
| Noise                                        | ✓      |                       |     |
| Coolant condition                            | ✓      |                       |     |
| Cooling performance                          | ✓      |                       |     |
| Radiator / Hoses (visual)                    | ✓      |                       |     |
| Transmission                                 |        |                       |     |
| Operation                                    | ✓      |                       |     |
| Noise                                        | ✓      |                       |     |
| Clutch                                       |        |                       | ✓   |
| CV joints                                    | ✓      |                       |     |
| Wheel bearings                               | ✓      |                       |     |
| Brakes                                       |        |                       |     |
| Performance                                  | ✓      |                       |     |
| Hand brake                                   | ✓      |                       |     |
| Tyres (lowest observed tread depth of tyres) |        |                       |     |
| Left front                                   | 5.0 mm |                       |     |
| Right front                                  | 5.5 mm |                       |     |
| Left rear                                    | 3.9 mm |                       |     |
| Right rear                                   | 4.0 mm |                       |     |
| Spare                                        | Yes    |                       |     |
| Suspension                                   |        |                       |     |
| Suspension performance                       | ✓      |                       |     |
| Steering performance                         | ✓      |                       |     |
| Shock absorbers                              | ✓      |                       |     |
| Air Conditioning / Heater                    |        |                       |     |
| Operation                                    | ✓      |                       |     |
| Electrical / Accessories                     |        |                       |     |
| Head lights                                  | ✓      |                       |     |
| Tail lights                                  | ✓      |                       |     |
| Indicators                                   | ✓      |                       |     |
| Dashboard warning lights                     | ✓      |                       |     |
| Wipers (front & rear)                        | ✓      |                       |     |
| Window winder FL                             | ✓      |                       |     |
| Window winder FR                             | ✓      |                       |     |
| Window winder RL                             | ✓      |                       |     |
| Window winder RR                             | ✓      |                       |     |
| Rear view mirrors                            | ✓      |                       |     |
| Radio (basic test only)                      | ✓      |                       |     |
| CD (basic test only)                         |        |                       | ✓   |
| Number of keys                               | 2      |                       |     |
| Central locking                              | ✓      |                       |     |
| Remote locking                               | ✓      |                       |     |
| Sat. nav. (basic test only)                  | ✓      |                       |     |
| Reversing camera                             | ✓      |                       |     |

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_