

Report ID:	28,384,702	Version:	2
Created:	08 Aug 2026		


Make:	Subaru	Model:	Legacy
Body Style:	Wagon	Year:	2010
Rego No.:	MRG802	Rego Expiry:	30 Sep 2024
WoF Expiry:	10 Apr 2024	Odometer:	163,086 Kms
Good No.:	28384702	VIN:	7AT0GF0BX19030740
Next Service:	151300	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both front sunshades missing, head unit not working, FR seat torn, windscreen stone chip inside cva, RR window switch not working, parcel blinds missing, all seats headrest missing,

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Engine oil leak, underbody surface rust, rotor disc rust, FL wheel play,

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Battery flat, service overdue, A/C not cooling,

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	☒ Yes ☐ No 99,000 Kms
Inspected by:	Curshey Accad
Published by:	Curshey Accad
Inspection Date:	08 Aug 2026

I have read and understood this condition guide:

NAME _____

SIGNATURE _____

	OK	Requires Attention	N/A
Engine			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings		✓	
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5 mm
Right front			5 mm
Left rear			6 mm
Right rear			6 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR		✓	
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera		✓	