


Make:	Hyundai	Model:	Veloster
Body Style:	Hatchback	Year:	2018
Rego No.:	LHC815	Rego Expiry:	28 Sep 2026
WoF Expiry:	28 Apr 2027	Odometer:	52,208 Kms
Good No.:	28384787	VIN:	KMHTC61EVJU318427
Next Service:	64575km	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comments	

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		☐ Yes	☐ No
Inspected by:	Robert Rankin		
Published by:	Luke Saunders		
Inspection Date:	11 Aug 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE