

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



### Front bumper needs a refit

Front wheel drive

|            |      |
|------------|------|
| Dashboard: | Good |
|------------|------|

## General Comments

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

**SIGNATURE**

|  |    |                       |     |
|--|----|-----------------------|-----|
|  | OK | Requires<br>Attention | N/A |
|--|----|-----------------------|-----|

|       |     |
|-------|-----|
| Spare | Yes |
|-------|-----|

|                  |   |  |  |
|------------------|---|--|--|
| Reversing camera | ✓ |  |  |
|------------------|---|--|--|