

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 28,407,141  | Version: | 2 |
| Created:   | 18 Sep 2026 |          |   |


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Mitsubishi  | Model:           | Outlander         |
| Body Style:   | SUV         | Year:            | 2007              |
| Rego No.:     | HTJ97       | Rego Expiry:     | 30 Nov 2026       |
| WoF Expiry:   | 27 Nov 2026 | Odometer:        | 254,810 Kms       |
| Good No.:     | 28407141    | VIN:             | 7AT0CJ3MX14105729 |
| Next Service: | 246800      | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Missing black plastic around right side spot light.  
Missing both back mud flaps.  
Paint faded on roof  
Missing tow bar younger

|                                   |     |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

## Under Carriage and Under Bonnet Inspection Comments

Exhaust cover rattles  
Over due service oil level low

## Interior Comments

|            |                                   |
|------------|-----------------------------------|
| Seats:     | Average                           |
| Carpets:   | Poor                              |
| Panels:    | Average                           |
| Dashboard: | steering wheel control don't work |

## General Comments

|                                   |                                                              |
|-----------------------------------|--------------------------------------------------------------|
| Road Conditions During Test Drive | Dry                                                          |
| Engine Timing Mechanism           | Timing Chain                                                 |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No Kms |
| Inspected by:                     | Melissa Wilson                                               |
| Published by:                     | Melissa Wilson                                               |
| Inspection Date:                  | 18 Sep 2026                                                  |

| OK | Requires Attention | N/A |
|----|--------------------|-----|
|----|--------------------|-----|

## Engine

|                           |   |   |  |
|---------------------------|---|---|--|
| Oil level                 |   | ✓ |  |
| Smoke & fumes             | ✓ |   |  |
| Engine performance        | ✓ |   |  |
| Noise                     | ✓ |   |  |
| Coolant condition         | ✓ |   |  |
| Cooling performance       | ✓ |   |  |
| Radiator / Hoses (visual) | ✓ |   |  |

## Transmission

|                |   |  |   |
|----------------|---|--|---|
| Operation      | ✓ |  |   |
| Noise          | ✓ |  |   |
| Clutch         |   |  | ✓ |
| CV joints      | ✓ |  |   |
| Wheel bearings | ✓ |  |   |

## Brakes

|             |   |  |  |
|-------------|---|--|--|
| Performance | ✓ |  |  |
| Hand brake  | ✓ |  |  |

## Tyres (lowest observed tread depth of tyres)

|             |      |
|-------------|------|
| Left front  | 1 mm |
| Right front | 2 mm |
| Left rear   | 3 mm |
| Right rear  | 4 mm |
| Spare       | Yes  |

## Suspension

|                        |   |  |  |
|------------------------|---|--|--|
| Suspension performance | ✓ |  |  |
| Steering performance   | ✓ |  |  |
| Shock absorbers        | ✓ |  |  |

## Air Conditioning / Heater

|           |   |  |  |
|-----------|---|--|--|
| Operation | ✓ |  |  |
|-----------|---|--|--|

## Electrical / Accessories

|                             |   |  |   |
|-----------------------------|---|--|---|
| Head lights                 | ✓ |  |   |
| Tail lights                 | ✓ |  |   |
| Indicators                  | ✓ |  |   |
| Dashboard warning lights    | ✓ |  |   |
| Wipers (front & rear)       | ✓ |  |   |
| Window winder FL            | ✓ |  |   |
| Window winder FR            | ✓ |  |   |
| Window winder RL            | ✓ |  |   |
| Window winder RR            | ✓ |  |   |
| Rear view mirrors           | ✓ |  |   |
| Radio (basic test only)     | ✓ |  |   |
| CD (basic test only)        | ✓ |  |   |
| Number of keys              | 2 |  |   |
| Central locking             | ✓ |  |   |
| Remote locking              | ✓ |  |   |
| Sat. nav. (basic test only) |   |  | ✓ |
| Reversing camera            | ✓ |  |   |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_