


Make:	Nissan	Model:	Navara
Body Style:	Utility	Year:	2024
Rego No.:	QTW839	Rego Expiry:	15 Jul 2026
WoF Expiry:	16 Sep 2027	Odometer:	44,046 Kms
Good No.:	28415812	VIN:	MNTCBND23A0031792
Next Service:	36342	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Front bumper left side damaged big dent and cracked/broken
Missing tow bar tongue
No key for hard lid

Under Carriage and Under Bonnet Inspection Comments

Over due a servicee

Seats:	drivers seat base pad worn holes, marks
Carpets:	Average
Panels:	wear
Dashboard:	Good

Missing brake pedal rubber

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____